

State Route 116 Storm Damage Repair Projects

September 5, 2006

1. West of Redwood Road near Northwood
 - The one way traffic control light was activated and work began on the project.
 - Crews are constructing a geosynthetic reinforced embankment.
2. East of Monte Rio
 - Riverside-Waler structure complete.
 - Uphill-Work is beginning uphill to insert soil nails. Drilling is taking place from a temporary dirt platform.
3. Monte Cristo Avenue
 - The one way traffic control light was activated.
 - Excavation/drilling for piles to be set at the retaining wall, consisting of studded I-beams embedded in concrete.
4. Just East Of Duncans Mills
 - Two way traffic control is in effect with a flagging operation as needed.
 - Concrete panels are in place and timber logging will be installed.
5. Just West Of Duncans Mills
 - Drilling continues, but there are some anomalies in the soil.
 - Crews are constructing a buttress or concrete cap beam on top of micropiles.